

## **Addendum to testo 350 Firmware USB, Bootloader, Update Guide**

Date: April 3, 2020

Subject: t350 Firmware Version 1.23 Issue; Display Configuration Altered

Upon updating the firmware with Version 1.23, the display of the 350 is altered with the addition of an unselected parameter. Typically, the additional parameter added is dP.

We recommend that whenever the 350 firmware is updated with Version 1.23, the 350 user should check the display and, if altered, manually restore the 350 display to its original display configuration. The display configuration can be modified from the Control Unit (Device Settings, Measurement View) or by using the easyEmission software (testo 350, Set up testo 350, Display set up).